

**INTERNATIONAL ROAD DYNAMICS INC.**702 43rd Street East, Saskatoon SK Canada

☎ 317-694-4224

- Site Service Report -**IRD SO.: 11167****IRD Contract No.:****From: Steve Schroeder****State: Maryland****Project Name/Location: Rt 15 Frederick, Md****Service Date(s): 3-10-10****Job Description: Perform annual site inspection.**

Work Completed: Drove to site. Performed visual inspection of sensors. Grout looks good. Sensors look good. Performed Electrical check. Found Loop one has a low shield resistance. Loop 1 is not spliced so I was unable to repair. Electrical check was otherwise good. I had Bruce Myers dial site to verify modem and site operations. Site is operating properly. Found that Plate one has a 0.0mV zero point but seems to be functioning fine.

Work Remaining: None**Parts Used:**

Part Name	Part Number	Quantity Used

Mileage : 295 miles**Hours Worked: 5 hours****Notes:****Action Items:**

Item	Action Required	Ownership
1.		
2.		
3.		
4.		